

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

TOP SECRET




Fig. 1




Fig. 3




Fig. 5




Fig. 6



6





Fig. 4 (12b)



12b Fig. 2 66




Fig. 7




Fig. 8

05898736-050404

FIG. 9





Fig. 9

TOP SECRET 92486850




Fig. 10



AS-1010-10  
7-10-700




Fig. 11




Fig. 13




Fig. 12A



Fig. 16





Fig. 14

Fig. 15





SECTION C-C

Fig. 17

09898736-090401

U.S. PATENT OFFICE  
 1965 JUN 15




Fig. 19




Fig. 18

Fig. 20

Fig. 21

TOP SECRET 9406060







Fig. 22



09090736-090404




Fig. 26




Fig. 30




Fig. 25




Fig. 29




Fig. 28






Fig. 27

104-112



106a Fig. 31



104 Fig. 32

09898736-090404




Fig. 33




Fig. 34






Fig. 35




Fig. 36




Fig. 37




Fig. 38




Fig. 39




Fig. 42

SECTION A-A




Fig. 40




Fig. 47

SECTION F-F




Fig. 41




Fig. 44





Fig. 43


009697-0044



cut at middle of clutch's teeth

SECTION C-C

Fig. 45



cut at bottom of clutch's teeth

SECTION E-E

Fig. 46

09998736-090464

FIG. 48




Fig. 48






Fig. 49





Patented Mar. 23, 1960






Fig. 58




Fig. 59




Fig. 60












Fig. 61









094060-924060




Fig. 71




Fig. 72

0958736-00444




Fig. 75




Fig. 77




Fig. 76




Fig. 78




Fig. 79

096336360




Fig. 80










Fig. 81

FIG. 82








Fig. 89




Fig. 90

09898736-090404

704050 96286860




Fig. 94




Fig. 92




Fig. 91




Fig. 93




Fig. 96




Fig. 95

